OMB Control No.: 2127-0004

Part 573 Safety Recall Report

16V-061

Manufacturer Name: Honda (American Honda Motor Co.)

Submission Date : JAN 29, 2016 **NHTSA Recall No. :** 16V-061

Manufacturer Recall No.: JX2, JX3, JX4



Manufacturer Information:

Manufacturer Name: Honda (American Honda Motor Co.)

Address: 1919 Torrance Blvd.

Torrance CA 90501

Company phone: 1-800-999-1009

Population:

Number of potentially involved: 2,230,000

Estimated percentage with defect: 0

Vehicle Information:

Vehicle: 2007-2011 Honda CR-V

Vehicle Type : Body Style :

Power Train: GAS

Descriptive Information: The recall population was determined based on manufacturing records and the

safety-defect set forth in Takata's notification to NHTSA (16E-005). The VIN range

reflects the vehicles that could potentially experience the problem.

Production Dates: JAN 01, 2007 - DEC 31, 2011

VIN (Vehicle Identification Number) Range

Begin: NR End: NR Not sequential VINs

Vehicle: 2011-2015 Honda CR-Z

Vehicle Type : Body Style :

Power Train: HYBRID ELECTRIC

Descriptive Information: The recall population was determined based on manufacturing records and the

safety-defect set forth in Takata's notification to NHTSA (16E-005). The VIN range

reflects the vehicles that could potentially experience the problem.

Production Dates: JAN 01, 2011 - DEC 31, 2015

VIN (Vehicle Identification Number) Range

Begin: NR End: NR Not sequential VINs

Vehicle: 2010-2014 Honda FCX Clarity

Vehicle Type : Body Style : Power Train : NR

-	n: The recall population was determined based on n safety-defect set forth in Takata's notification to N reflects the vehicles that could potentially experie 01, 2010 - DEC 31, 2014	NHTSA (16E-005). The VIN range
	, , , , , , , , , , , , , , , , , , ,	
VIN (Vehicle Identifica	ation Number) Range	
Begin : NR	End : NR	☐ Not sequential VINs
Vehicle: 2009-2013 He Vehicle Type:	onda Fit	
Body Style :		
Power Train : GAS		
-	n: The recall population was determined based on n safety-defect set forth in Takata's notification to N reflects the vehicles that could potentially experie 01, 2009 - DEC 31, 2013	NHTSA (16E-005). The VIN range
VIN (Vehicle Identifica	ation Number) Range	
Begin: NR	End : NR	☐ Not sequential VINs
-		NHTSA (16E-005). The VIN range
VIN (Vehicle Identifica	ation Number) Range	
Begin : NR	End : NR	☐ Not sequential VINs
•	G	NHTSA (16E-005). The VIN range
VIN (Vehicle Identifica		
Begin : NR	End : NR	☐ Not sequential VINs

Vehicle: 2007-2014 Hor Vehicle Type: Body Style: Power Train: GAS	nda Ridgeline	
Descriptive Information Production Dates : JAN 0	The recall population was determined based on manusafety-defect set forth in Takata's notification to NHTS reflects the vehicles that could potentially experience 1, 2007 - DEC 31, 2014	SA (16E-005). The VIN range
VIN (Vehicle Identificat		
Begin: NR	End : NR	☐ Not sequential VINs
Production Dates : JAN 0	: The recall population was determined based on manusafety-defect set forth in Takata's notification to NHTS reflects the vehicles that could potentially experience 1, 2013 - JAN 29, 2016	SA (16E-005). The VIN range
VIN (Vehicle Identificat	tion Number) Range	
Begin: NR	End : NR	☐ Not sequential VINs
Vehicle: 2013-2014 Act Vehicle Type: Body Style: Power Train: HYBRID EI Descriptive Information	LECTRIC : The recall population was determined based on manusisafety-defect set forth in Takata's notification to NHTS reflects the vehicles that could potentially experience	SA (16E-005). The VIN range
VIN (Vehicle Identificat	tion Number) Range	
Begin: NR	End : NR	☐ Not sequential VINs
Vehicle: 2007-2016 Active Vehicle Type: Body Style: Power Train: GAS Descriptive Information Production Dates: JAN 0	: The recall population was determined based on manusafety-defect set forth in Takata's notification to NHTS reflects the vehicles that could potentially experience	SA (16E-005). The VIN range

VIN (Vehicle Identification N	umber) Range	
Begin : NR	End: NR	☐ Not sequential VINs
Vehicle: 2005-2012 Acura RI		
Vehicle Type :		
Body Style :		
Power Train : GAS		
safet	recall population was determined based y-defect set forth in Takata's notification cts the vehicles that could potentially ex 15 - DEC 31, 2012	n to NHTSA (16E-005). The VIN range
VIN (Vehicle Identification N	·	
Begin : NR	End: NR	☐ Not sequential VINs
Vehicle: 2009-2014 Acura TL		
Vehicle Type :		
Body Style :		
Power Train : GAS		
safet	recall population was determined based y-defect set forth in Takata's notification cts the vehicles that could potentially ex 19 - DEC 31, 2014	n to NHTSA (16E-005). The VIN range
VIN (Vehicle Identification N		
Begin : NR	End : NR	☐ Not sequential VINs
Vehicle: 2010-2013 Acura ZD	X	
Vehicle Type :		
Body Style :		
Power Train : GAS		
safet	recall population was determined based y-defect set forth in Takata's notification cts the vehicles that could potentially ex	n to NHTSA (16E-005). The VIN range
Production Dates : JAN 01, 201		perience the problem.
VIN (Vehicle Identification N	umber) Range	
	End : NR	☐ Not sequential VINs

Description of the Defect: According to the equipment defect notification (16E-005) filed by Takata, the propellant tablets in some of the subject inflators may experience an alteration over time, which could potentially lead to over-aggressive combustion in the event of an air bag deployment.

FMVSS 1:NR FMVSS 2:NR

Description of the Safety Risk: Depending on the circumstances, this potential condition could create excessive

internal pressure when the airbag is deployed, which could result in the body of

the inflator rupturing upon deployment.

Description of the Cause: Based upon Takata's investigation to date, the potential for such ruptures may occur

in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity. In addition, Takata is aware of four test ruptures in ballistic tests of non-desiccated PSDI-5 inflators, but not aware of any field incidents in which a PSDI-5 inflator has ruptured (desiccated or non-

desiccated). The potential for rupture may also be influenced by other factors,

including manufacturing variability.

Identification of Any Warning that can Occur: NR

Supplier Identification:

Component Manufacturer

Name: T.K. Holdings, Inc. Address: 888 16th Street NW

Suite 800 Washington DISTRICT OF COLUMBIA 20006

Country: United States

Chronology:

January 25, 2016

Takata submitted an equipment defect notification (16E-005) to NHTSA that identified a safety related defect in the subject driver frontal airbag inflators. A copy of Takata's notification was received by Honda on January 25, 2016.

January 28, 2016

Based on the determination by Takata that a safety-related defect exists in the subject inflators, as set forth in the equipment defect notification (16E-005) filed by Takata on January 25, 2016, Honda Motor Co., Ltd., determined a safety defect exists and decided to conduct a safety recall.

Description of Remedy:

Description of Remedy Program: A new inflator will be installed in affected vehicles, without charge.

However, due to the large volume of new inflators needed to repair vehicles, the necessary parts will not be available until Fall 2016. As a result, owners of affected vehicles will be informed of the recall in an initial notification letter. Once replacement parts become available Honda will send a second notification letter to owners. The second round of notifications will begin with older model year vehicles located in Honda's previously defined HAH region and will expand accordingly as more parts become available.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production: NR

Recall Schedule:

Description of Recall Schedule : Owner notification is TBD as of 1/26/2016

Planned Dealer Notification Date : JAN 29, 2016 - NR

Planned Owner Notification Date: NR - NR

* NR - Not Reported